



Quartus II Software Release Notes

December 2002

Quartus II version 2.2

This document provides late-breaking information about the following areas of this version of the Altera® Quartus® II software. For information about memory, disk space, and system requirements, refer to the **readme.txt** file in your **quartus** directory.

New Features & Enhancements	2
Device Support & Pin-Out Status	2
Full Device Support.....	2
Advance Device Support.....	3
Initial Information Support.....	3
Timing Models	4
Preliminary Timing Models	4
Final Timing Models	4
EDA Interface Information	6
Known Issues & Workarounds.....	7
General Quartus II Software Issues	7
Platform-Specific Issues.....	13
Device Family Issues.....	21
Design Flow Issues.....	26
EDA Integration Issues	33
Customer Service Requests Resolved	34

New Features & Enhancements

The Quartus II software version 2.2 is now even easier to use and increases SOPC design productivity with the following new features and enhancements:

- Redesigned user interface makes the Quartus II software even easier to use (includes new Assignments menu, Assignment Editor, and reorganized File, Project, Tools, and Processing menus)
- New Memory Compiler interface for creating memory in all supported device families
- New Fitter timing netlist optimization that uses post-fitting timing information to increase the design performance of some designs by as much as 20%
- New incremental routing capability for the SignalTap[®] II embedded logic analyzer so you can add or change nodes without requiring a full recompilation
- Advance support for the new Stratix[™] GX device family
- Option to maintain design hierarchy in simulation output netlists
- Stratix[™] design-specific IBIS model generation
- PowerGauge[™] power analysis for user-specifiable start and stop times
- Tutorial modules can now be printed easily from within the Tutorial

Device Support & Pin-Out Status

Full Device Support

Full compilation, simulation, timing analysis, and programming support is now available for the following new devices and device packages:

Devices with Full Support

Device Family	Devices	
Stratix	EP1S20 F780	EP1S20 F672
	EP1S20 B672	EP1S30 F780
	EP1S30 B956	EP1S30 F1020
	EP1S40ES B956	EP1S40ES F1020
	EP1S40ES F1508	EP1S80 B956
	EP1S80 F1508	

Advance Device Support

Compilation, simulation, and timing analysis support is provided for the following devices that will be released in the near future. Although the Compiler generates pin-out information for these devices, it does not generate programming files for them in this release.

Devices with Advance Support

Device Family	Devices	
Cyclone™	EP1C6 F256	EP1C12 F256
Stratix	EP1S10ES F484	EP1S20 F484
	EP1S10 F484	EP1S40 B956
	EP1S40 F1020	EP1S40 F1508
Stratix GX	EP1SGX10 CF672	EP1SGX10 DF672
	EP1SGX25 CF672	EP1SGX25 DF672
	EP1SGX25 CF1020	EP1SGX25 DF1020
	EP1SGX40 DF1020	EP1SGX40 GF1020

Initial Information Support

Compilation, simulation, and timing analysis support is provided for the following devices that will be released in the near future. Programming files and pin-out information, however, are not generated for these devices in this release.

Devices with Initial Information Support

Device Family	Devices
None	

Timing Models

This section contains a summary of timing model status in the current version of the Quartus II software.

Preliminary Timing Models

The following table shows the devices with preliminary timing models in the current version of the Quartus II software:

Devices with Preliminary Timing Models

Device Family	Device	Notes
Stratix	EP1S10	The Quartus II software version 2.2 includes preliminary timing models for -5, -6, and -7 speed grades for the Stratix device family.
	EP1S20	
	EP1S25	
	EP1S30	
	EP1S40	
	EP1S60	
	EP1S80	
Stratix GX	EP1SGX10	
	EP1SGX25	
	EP1SGX40	
Cyclone	EP1C3	
	EP1C6	
	EP1C12	
	EP1C20	

Final Timing Models

The following table lists the devices with final timing models that are available in the current version of the Quartus II software:

Devices with Final Timing Models

Device Family	Device	Timing Models Final in Quartus II Version Number
APEX™ II	EP2A15	2.1
	EP2A25	2.1
	EP2A40	2.1
	EP2A70	2.1
APEX™ 20KC	EP20K200C	2.0 SP1
	EP20K400C	2.0
	EP20K600C	2.0
	EP20K1000C	2.0 SP1
Excalibur™	EPXA1	2.0 SP2
	EPXA4	2.0 SP2
	EPXA10	2.0 SP1
Mercury™	EP1M350	2.0
	EP1M120	2.1 SP1
MAX™ 7000	EPM7032AE	2.0
	EPM7064AE	2.0
	EPM7128AE	2.0
	EPM7256AE	2.0
	EPM7512AE	2.0
	EPM7032B	2.0
	EPM7064B	2.0
	EPM7128B	2.0
	EPM7256B	2.0
	EPM7512B	2.1 SP1
MAX 3000	EPM3032A	2.0
	EPM3064A	2.0
	EPM3128A	2.0
	EPM3256A	2.0
	EPM3512A	2.1 SP1

The current version of the Quartus II software also includes final timing models for the, ACEX® 1K, APEX 20KE, FLEX® 6000, and the FLEX 10KE device families. Final timing models for these device families became final in versions earlier than version 2.0.

EDA Interface Information

The Quartus II software version 2.2 supports the following EDA tools.

Supported EDA Tools

Synthesis Tools	Version	NativeLink[®] support
Mentor Graphics [®] LeonardoSpectrum [™] -Altera	2002e	✓
Mentor Graphics [®] LeonardoSpectrum [™]	2002e	✓
Synopsys Design Compiler	2002.02	
Synopsys FPGA Compiler II	3.7	✓
Synplicity Synplify and Synplify Pro	7.2	✓
Aplus Design Technologies (ADT) PALACE [™]	2.1	✓
Verification Tools	Version	NativeLink support
Cadence NC-Verilog	3.4	✓
Cadence NC-VHDL	3.4	✓
Cadence Verilog-XL	3.3	
Model Technology [™] ModelSim [®]	5.6a	✓
Model Technology ModelSim-Altera	5.6a	✓
Innoveda BLAST	1.2.2	
Synopsys PrimeTime	2000.05	✓
Synopsys Scirocco	2000.12	✓
Synopsys VSS	2000.05	
Synopsys VCS	6.0.1	
Mentor Graphics Tau	2.2	
Verplex Conformal LEC	3.4.0.a	

Known Issues & Workarounds

General Quartus II Software Issues

Issue	Workaround
<p>The Quartus II software no longer uses the registry to store non-user interface-related settings. Non-user interface-related settings are stored automatically in the quartusii.ini file when you open the Quartus II software user interface for the first time.</p>	<p>You must open the Quartus II software user interface at least once before using the command-line version of the software.</p>
<p>Versions of the Quartus II software earlier than version 2.0 cannot open Block Design Files (.bdf) created with the Quartus II software version 2.0 and later.</p>	
<p>Not all speed grades of a given device share the same features.</p>	<p>Refer to the Altera data sheet for the device family for further information.</p>
<p>The default setting for the Power-Up Don't Care logic option has been changed to On in the Quartus II software version 2.1 Service Pack 1 and later.</p>	
<p>There is no distinction between output ports and bidirectional ports in AHDL Function Prototypes; instead, all ports listed after the RETURNS keyword are treated as output ports. As a result, if you specify a bidirectional port in a logic function's Function Prototype Statement and do not connect the port to a top-level bidirectional pin or to other logic in the design where you instantiate the logic function, an error can occur.</p>	<p>Connect the port to a top-level bidirectional pin or to other logic in the design.</p>
<p>To use the EP20K400GC655 device in your design, please contact the Altera Customer Applications Department.</p>	
<p>If you have a version of the Quartus[®] software earlier than the Quartus II software version 1.0 installed on your computer in addition to the Quartus II software, you can start the previous version of the program only by running the runq.exe program from the \quartus\bin directory that contains the earlier version you wish to use.</p>	

Issue	Workaround
<p>You should not create multiple Compiler settings that have the same design entity as the “compilation focus.”</p>	
<p>Under some circumstances, if the Optimize I/O cell register placement for timing option in the Compiler Settings page of the Settings dialog box (Assignments menu) is turned on and you are using multiple peripheral clock enable signals, you may receive an error message or the Quartus II software may crash.</p>	<p>Set the Clock Enable Routing logic option to Single-Pin for some of the clock enable signals.</p>
<p>Context-sensitive Help is not available for some items in the Quartus II software.</p>	<p>To locate Help on those items, choose Index from the Help menu and type the name of the item.</p>
<p>For APEX 20KE devices, the Quartus II software provides limited support for the following I/O standards that are not available with the I/O Standard logic option:</p> <ul style="list-style-type: none"> • LVPECL is a differential I/O standard that is similar to the LVDS I/O standard. APEX 20KE devices can support LVPECL I/O pins by using the I/O pins in LVDS mode with an external resistor network. • PCI-X is an enhanced version of the PCI I/O standard that can support a higher average bandwidth. This standard has more stringent requirements than PCI. 	<p>To use the LVPECL I/O standard in APEX 20KE devices in the Quartus II software, set the I/O Standard logic option for the pins to LVDS and connect the pins to an appropriate external resistor network.</p> <p>The APEX 20KE I/O drivers meet the requirements for PCI-X. Turn on the PCI I/O logic option to support PCI-X requirements, including the overshoot clamp.</p>
<p>You cannot locate the source of an error in a design file if compilation was unsuccessful due to a syntax error.</p>	
<p>If you open a project that was created using an earlier version of the Quartus II software, you may receive a message that indicates that the database is incompatible and that results of the last compilation will be lost.</p>	<p>To maintain existing placement information, back-annotate all of the project assignments in the earlier version. Then, delete the <code>\<project name>\db</code> directory and all of its contents.</p>
<p>The Timing Analyzer does not recognize non-PLL clock signals when using any PLL megafunction.</p>	<p>Make clock settings assignments to all non-PLL clocks.</p>

Issue	Workaround
<p>If you are using the <code>lpm_mult</code> megafunction, you must turn off the Auto Cascade Chains option when editing project defaults in the Default Logic Options page of the Settings dialog box (Assignments menu).</p>	
<p>The Waveform editor does not allow you to create a bus with nodes that are nonconsecutive members of a bus.</p>	<p>Create buses only with nodes that are consecutive members of a bus. Or, use the Group command (Edit menu) to create groups of arbitrary nodes.</p>
<p>Using the Cancel button in the Assignment Organizer (Tools menu) when multiple nodes have been selected causes the Quartus II software to restore the setting(s) of the first node to all the nodes that were edited.</p>	<p>Do not use the Cancel button to cancel changes made to two or more selected nodes that have assignments of differing settings.</p>
<p>If you are using the <code>altcam</code>, <code>altclklock</code>, <code>altlvds_rx</code>, or <code>altlvds_tx</code> megafunctions, the equations shown in the Equations Section of the Compilation Report are not complete.</p>	<p>To view the complete equations for any of these megafunctions, use the Equations window of the Last Compilation floorplan.</p>
<p>The Quartus II software does not support file names with more than one extension. For example, you cannot use the file name file.eda.edif.</p>	<p>Use file names with only one extension.</p>
<p>If you install the Quartus II software for PCs on a UNIX server that exports shares with the Samba software version 1.9.18p10, you may experience problems accessing project files also on the network.</p>	<p>Altera recommends using version 1.9.16p11 or 2.0 of the Samba software.</p>
<p>If you make assignments to reserve pins as a group or with group notation (<code>debug[7..0]</code>), the Quartus II software does not correctly generate simulation output files, and you receive a warning message saying “Unsupported data type in the top-level module.”</p>	<p>Reserve the pins using single name notation (e.g., <code>debug7</code>, <code>debug6</code>, and so on).</p>
<p>The Quartus II software versions 2.1 and later supports only version 5.2 and later of the Altera PowerKit™ software. Previous versions of the PowerKit software are not supported with these versions of the Quartus II software.</p>	

Issue	Workaround
<p>Under some circumstances, an error message saying “Can’t start server. Beginning attempt 1/3...” appears when starting a compilation, simulation, or software build.</p>	<p>Increase the value of the environment variable <code>QUARTUS_PROCESS_TIMEOUT</code> from the default value of 100. If the environment variable does not exist, set it to an initial value of 200. You may have to increase the value until you no longer receive the error message.</p>
<p>If you are using the HSTL Class II I/O standard with an APEX II device, additional information is required.</p>	<p>Contact the Altera Customer Applications department at apexii@altera.com for information about Service Packs and device pin-outs.</p>
<p>Do not change the file permissions (such as changing “read-only” to “read and write”) of Quartus II settings and configurations files (<code>.csf</code>, <code>.esf</code>, and so on) while a Quartus II project is open.</p>	<p>Close your Quartus II project before making changes to the file permissions.</p>
<p>The order of ports for the ARM[®]-based Excalibur MegaWizard[®] Plug In-generated symbol for the stripe changed in version 2.0 of the Quartus II software. If you re-run the MegaWizard Plug-In Manager (Tools menu) for a design created in a version of the Quartus II software earlier than version 2.0, you will receive port connection errors when you compile the design.</p>	<p>To avoid receiving these errors, adjust the port connections in the BDF after updating the symbol.</p>
<p>Node names containing numbers greater than $2^{31}-1$ (2147483647) will cause an Internal Error in the Quartus II software.</p>	<p>Do not use node names containing large numbers.</p>
<p>Occasionally the Programmer does not allow you to use a MAX 7000AE Programmer Output File (<code>.pof</code>) with a MAX 7000AE device. This error sometimes occurs after a compatible MAX 7000B device is used with the MAX 7000AE POF.</p>	<p>Do not switch between compatible MAX 7000B and MAX 7000AE devices when a MAX 7000AE POF is loaded, or reload the MAX 7000AE POF.</p>
<p>The Quartus II software versions 2.1 and later no longer support the Compiler Settings File (<code>.csf</code>) <code>MIGRATION_DEVICES</code> variable.</p>	<p>In order to specify migration device names in the CSF, use the <code>DEVICE_MIGRATION_LIST</code> variable. For example: <code>DEVICE_MIGRATION_LIST =</code> <code>"DEVICE_A,DEVICE_B,DEVICE_C" ;</code></p>

Issue	Workaround
<p>Routing back-annotation may fail if the back-annotated locations do not match the location assignments in the CSF or if the location assignments are missing. This problem can occur if you change devices, or if you remove some location assignments by using the Assignment Organizer (Tools menu) or by manually editing the CSF.</p>	<p>If you experience a “no fit” or an Internal Error while using routing back-annotation, delete the Routing Constraints File (.rcf) and back-annotate the design again after a successful compilation.</p>
<p>After register duplication has occurred, the duplicated register has a unique name in the form <i><original name>~<suffix></i>. The new register name may not properly inherit timing assignments made with wild cards.</p>	<p>Make sure that duplicated register names are included in your wild card match when making timing assignments.</p>
<p>You may receive an “invalid command name” error when you run an existing Tcl script that uses the Tk toolkit for its user interface. Beginning with the Quartus II version 2.2 software release, the Quartus II software no longer initializes the Tk toolkit automatically when starting any process.</p>	<p>Add the Tcl command “init_tk” to the beginning of any Tcl script that uses Tk.</p>
<p>The lpm_fifo MegaWizard Plug-In has been removed from the Quartus II software version 2.2 release. The <code>lpm_fifo</code> megafunction is still included for backward compatibility with older designs.</p>	<p>Altera recommends that you use the lpm_fifo+ MegaWizard Plug-In for all new designs requiring single-clock FIFO functions.</p>
<p>If you receive an error message saying “System resources low...” or if the user interface is slow in responding and there is a lot of disk activity when you are not compiling a design, your system may be running out of free memory.</p>	<p>You can recover system memory by clearing messages from the Messages window. To clear messages from the Messages window, right-click anywhere in the Messages window and choose Clear Messages from Window (right button pop-up menu). Additional memory can be recovered by closing the Floorplan Editor.</p>
<p>Occasionally, the Quartus II software may crash or hang with no error message immediately upon opening a project.</p>	<p>Delete the Quartus Workspace File (.qws) <i><project name>.qws</i> from the project directory. If the problem persists, delete the <i><project directory>\db</i> directory.</p>

Issue	Workaround
<p>When you are setting phase shift and duty cycle values for clock signals using the <code>altpll</code> megafunction, some combinations of settings may result in values that cannot be synthesized exactly. Under certain circumstances, the Quartus II software attempts to synthesize the phase shift parameter before the duty cycle parameter.</p>	<p>You should first select values for the parameter (phase shift or duty cycle) that is most important for your design.</p>
<p>Altera recommends that you not use the Project Navigator to remove the top-level design entity from your project. Doing so will cause the Quartus II software to crash with an Internal Error during compilation.</p>	
<p>If you are using the Quartus II Web Edition software version 2.2, the software may crash if you compile a design while the Current Assignments Floorplan is open.</p>	<p>Close the Current Assignments Floorplan before compiling the design.</p>

Platform-Specific Issues

PC Only

Issue	Workaround
<p>Under certain circumstances, the Quartus II installation program may crash or you may receive an error message immediately upon launching the installation program.</p>	<p>Reinstall the stdole32.tlb file from the original Windows distribution disks. To reinstall the file, type the appropriate command at a command prompt. (Note: the command must be typed on one line.)</p> <p>Windows 98: <CD-ROM drive letter>:\win98\extract.exe /A /L %SystemRoot%\System base4.cab stdole32.tlb <Enter></p> <p>Windows 98SE: <CD-ROM drive letter>:\extract.exe /A /L %SystemRoot%\System base4.cab stdole32.tlb <Enter></p> <p>Windows NT: <CD-ROM drive letter>:\i386\expand.exe stdole32.tl_ %SystemRoot%\System32\stdole32.tlb <Enter></p> <p>Windows 2000: <CD-ROM drive letter>:\i386\expand.exe stdole32.tl_ %SystemRoot%\System32\stdole32.tlb <Enter></p> <p>Windows XP: <CD-ROM drive letter>:\i386\expand.exe stdole32.tl_ %SystemRoot%\System32\stdole32.tlb <Enter></p>
<p>It is possible that one of the Quartus II executable files (quartus.exe, quartus_cmd.exe, quartus_swb.exe, quartus_dbc.exe, quartus_sim.exe, or quartus_cmp.exe) may not terminate properly after an error.</p>	<p>Use the Windows Task Manager to end the process before running the Quartus II software again.</p>

Issue	Workaround
<p>If the full, hierarchical name of an instance exceeds 247 characters, it may not be displayed properly in the Quartus II user interface. This problem occurs most often with EDIF netlist files generated by other EDA synthesis tools.</p>	<p>Limit the full, hierarchical instance name to fewer than 247 characters if possible.</p>
<p>If you are running the Quartus II software under the Windows 2000 operating system using a node-locked (single-user) license that is locked to a network interface card number (NIC ID), and are not physically connected to the network, the Quartus II software will not be able to determine your NIC ID and will not allow you to compile a design. This problem also occurs if you are running a FLEXlm license server under the Windows 2000 operating system with a license locked to the NIC ID.</p>	<p>Follow the recommendations given on the following Microsoft Knowledge Base web page: http://support.microsoft.com/support/kb/articles/Q239/9/24.asp</p>
<p>The Quartus II software will not operate if your computer has multiple active network interface cards (NICs).</p>	<p>If you have more than one NIC, you must deactivate all but one in order to run the Quartus II software.</p>
<p>A Japanese-language version of the online Help file for the Quartus II software version 1.0 is included on the Quartus II software CD-ROM. You can use the Japanese online Help with the current version of the Quartus II software, but not all Help information will be up-to-date.</p>	<p>To use the Japanese online Help, copy the quartus.chm file from the jhlp directory of the CD-ROM to your \quartus\bin directory.</p>
<p>If you are running the Quartus II software from a network server, the Quartus II software will not run properly on the client computer if you share the \quartus\bin directory.</p>	<p>You must share the quartus directory, not the \quartus\bin directory.</p>
<p>If you are running the ZoneAlarm personal firewall software, you may receive a message saying, "Can't start or continue to run database creator" when you launch the Quartus II software.</p>	<p>The Quartus II software is not compatible with the ZoneAlarm software. The ZoneAlarm software mistakenly determines that the Quartus II software is accessing the Internet when it uses TCP/IP for its inter-process communication. You must disable the ZoneAlarm software to run the Quartus II software.</p>

Issue	Workaround
The Quartus II software installation program does not add the path for the Quartus II software to the PATH statement in your autoexec.bat file when installed under Windows 98.	Add the path for your installed Quartus II software to the PATH statement in your autoexec.bat file manually.
Under some circumstances, the Quartus II software crashes when using the “X” button to close the Print Preview window if a project is open.	Use the Close button to close the Print Preview window if you have a project open.
If you disconnect your network connection while the Quartus II software is open, you may receive an error message saying “Can't start or continue to run the db creator.”	Close the Quartus II software before disconnecting the network connection and wait for the “LAN is disconnected” message in the Windows Taskbar before restarting the Quartus II software.
The Quartus II software is not compatible with the MATLAB web server.	Turn off the MATLAB web server in the Services Control Panel (Start menu) before running the Quartus II software.
Under some circumstances, the Quartus II splash screen appears and the Quartus II icon appears in the Taskbar, but the graphical user interface does not appear.	The registry settings controlling the position of the Quartus II windows may have become corrupted. Type the following command at a command prompt: <code>quartus -reset_desktop <Enter></code>
Path names longer than 229 characters can cause an internal error in the Quartus II software.	Make sure that all path names do not exceed 229 characters.
Under some circumstances, the Quartus II software may run correctly the first time it is started after installation, then fail to run with a “License Not Found” error thereafter.	If you have specified multiple license servers in either your LM_LICENSE_FILE environment variable or on the License Setup page of the Options dialog box (Tools menu), you must make the license server that serves the Quartus II software license the first server specified on the line.
On computers running the Windows 98 or Windows 98SE operating system, downloading device data at speeds less than 57,600 baud can result in failed downloads.	Download device data at speeds of 57,600 baud or greater when operating under Windows 98 or Windows 98SE.

Solaris, HP-UX & Linux

Issue	Workaround
The Quartus II Help is not available if you have set either the MWNO_RIT or the MWDONT_XINITTHREAD environment variables before running the Quartus II software.	Remove the variables from your environment and allow the Quartus II software to set these variables automatically, if needed.
If you are using the Exceed X server software for Windows while running the Quartus II software, the font size may be larger than the line height. This problem occurs most often if you installed the Exceed software while running at a screen resolution greater than 1024 × 768.	Reinstall the Exceed software while running at a screen resolution of 1024 × 768. You can then switch back to your normal, higher resolution setting.
Under some circumstances, there may be editor windows listed in the Window menu that you cannot see.	To display the hidden windows, choose Cascade (Window menu).
You cannot launch the AXD Debugger software from within the Quartus II software.	Launch the AXD Debugger software from outside the Quartus II software.
If you use the License Setup page of the Options dialog box (Tools menu) to enter the location of the license file, the Quartus II software may give an “Unable to Find License” message.	Restart the Quartus II software before compiling your design.
Under some circumstances, the Internet connectivity features of the Quartus II software are not functional.	Specify the full path to your web browser software on the Internet Connectivity page of the Options dialog box (Tools menu). If you access the Internet through a proxy server, you must also specify the address of the proxy server and its port number.
The Colors list in the Block & Symbol Editor Color Options page of the Options dialog box (Tools menu) or Format tab of the Properties dialog box (Edit menu) for any object in the Block or Symbol Editors may remain open, and may cause an internal error if you click anywhere else in the Quartus II software before closing the Colors list box.	Select a color to close the Color list box.
You cannot run the Innoveda BLAST software automatically from within the Quartus II software, even if the Run this tool automatically after compilation option is turned on.	Run the Innoveda BLAST software manually outside the Quartus II software.

Issue	Workaround
You cannot run the Mentor Graphics LeonardoSpectrum software from within the Quartus II software even if the Run this tool automatically after compilation option is turned on.	Run the LeonardoSpectrum software manually outside the Quartus II software.
You cannot run the Model Technology ModelSim software from the EDA Tool Post-Compilations Options > Run Simulation Tool command (Processing menu) from within the Quartus II software.	Run the ModelSim software outside the Quartus II software.
You can access the Quartus II online Help by typing <code>hh quartus.chm</code> <Return> at a command prompt.	
If you right-click on a menu item after clicking on it with the left mouse button, the Quartus II software may hang and become unresponsive.	You must kill the process and restart the Quartus II software.
If you attempt to exit from the Quartus II software while the Tutorial window is open, the Tutorial window may remain open and may not respond to your commands.	Close the Tutorial window before exiting from the Quartus II software.
When the LogicLock Regions window is floating, you cannot drag and drop node names to it from the Node Finder.	Dock the LogicLock Regions window before dragging node names to it from the Node Finder.

Solaris Only

Issue	Workaround
The ARM-Based Excalibur MegaWizard Plug-In , which is available from the MegaWizard Plug-In Manager requires the Java Runtime Environment (JRE) version 1.3, which has already been installed on your computer. On Solaris workstations, however, you may need to install extra patches to the operating system in order for JRE 1.3 to function properly.	Check the web site http://java.sun.com/j2se/1.3/install-solaris-patches.html for information about any patches that might be needed.

Issue	Workaround
A Japanese-language version of the online Help file for the Quartus II software version 1.0 is included on the Quartus II software CD-ROM. You can use the Japanese online Help with the current version of the Quartus II software, but not all Help information will be up to date.	To use the Japanese online Help, copy the quartus.chm file from the jhhelp directory of the CD-ROM to your /quartus/solaris directory.
If you attempt to exit from the Quartus II software while the Tutorial window is open, the Tutorial window may remain open and may not respond to your commands.	Close the Tutorial window before exiting from the Quartus II software.

HP-UX Only

Issue	Workaround
You receive error messages indicating that you do not have required permissions to perform the requested operation while using Network Information Services (NIS).	Add a plus-sign (+) followed by a carriage return on a line by itself as the last line in both of the following files: /etc/passwd and /etc/group .
Attempting to convert your device SRAM Object Files (.sof) to Programmer Output Files (.pof) for use with a configuration device, such as an EPC2 device, causes the Quartus II software to “hang” when you open the Conversion Setup File (.cof).	Create the POF as usual and add it to your project with the Add Files to Project command (Project menu).
A Japanese-language version of the online Help file for the Quartus II software version 1.0 is included on the Quartus II software CD-ROM. You can use the Japanese online Help with the current version of the Quartus II software, but not all Help information will be up-to-date.	To use the Japanese online Help, copy the quartus.chm file from the jhhelp directory of the CD-ROM to your /quartus/hp11 directory.
Under some circumstances the Quartus II user interface may “hang” and become unresponsive during compilation on an HP-UX 10.2 workstation. This problem occurs due to a problem in HP-UX 10.2 and does not occur when running on HP-UX 11.0.	Upgrade to HP-UX 11.0; the problem does not occur when running on HP-UX 11.0. <i>or</i> Kill the existing <code>quartus</code> process and recompile the project using the command-line. You can then use the UI to view the compilation results.

Linux Only

Issue	Workaround
<p>The MegaWizard Plug-In Manager (Tools menu) may initially appear very small or the Quartus II software may appear to be frozen when you are accessing the Linux version of the Quartus II software using Exceed and the KDE windows manager.</p>	<p>Replace the Java Runtime Environment (JRE) that is installed automatically with the Quartus II software with the JRE version 1.4, which is available at the following URL: http://java.sun.com/j2se/1.4/download.html Run the JRE installation script in a temporary directory to unarchive the JRE version 1.4. Then, make a backup copy of your /quartus/linux/jre1.3.1_02 directory. Next, copy the contents of the temporary directory to your /quartus/linux/jre1.3.1_02 directory, keeping the directory name the same, even though you are using the JRE version 1.4.</p>
<p>A Japanese-language version of the online Help file for the Quartus II software version 1.0 is included on the Quartus II software CD-ROM. You can use the Japanese online Help with the current version of the Quartus II software, but not all Help information will be up-to-date.</p>	<p>To use the Japanese online Help, copy the quartus.chm file from the jhhelp directory of the CD-ROM to your /quartus/linux directory.</p>
<p>If the MasterBlaster™ download cable is not listed in the Available hardware items list in the Hardware Settings tab of the Hardware Setup dialog box, but it is connected properly, you may not have read/write permission for the serial (/dev/ttySx) port to which the MasterBlaster cable is connected.</p>	<p>Have a system administrator assign read/write permission for the appropriate port. This change can be accomplished by adding you to the “uucp” group, or by giving read/write permission for the serial port to everyone, using the following command: <code>chmod o+rw /dev/ttySx</code> where <i>x</i> is the serial port affected.</p>
<p>This release of the Quartus II software supports the ByteBlasterMV download cable using either Passive Serial or JTAG modes. Although you can generate Jam Files (.jam) and Jam Byte-Code Files (.jbc), these file types are not supported for device configuration on Red Hat Linux version 7.1. Additionally, the EPC4, EPC8, and EPC16 configuration devices are not supported at this time, and programming times of EPC2 devices may be extremely slow.</p>	<p>For information about using a ByteBlasterMV download cable with the Quartus II software on the Linux operating system, refer to the <i>Quartus II Installation & Licensing Manual for UNIX and Linux Workstations</i>, or contact Altera Customer Applications.</p>

Issue	Workaround
<p>If you are using the ReflectionX X server software as your display on a Linux workstation, the Quartus II software may hang and a white box may appear.</p>	<p>Set the <code>QUARTUS_MWWM</code> environment variable to <code>allwm</code> and then start the Quartus II software without the splash screen by typing the following commands at a command prompt: <code>setenv QUARTUS_MWWM allwm <Enter></code> <code>quartus -no_splash <Return></code></p>
<p>Do not use drag and drop within the programming list in the Programmer window to add or duplicate a file or device. Doing so will cause the Quartus II software to crash with an internal error.</p>	<p>Use the Add File or Add Device command and select the device or file to add.</p>
<p>The Quartus II software may crash if you enter a value outside the acceptable range in the Guideline spacing box in the Block/Symbol Editor General Options page or in the Width controls in the Waveform Editor Printing Options page or in the Default file size controls in the Memory Editor General Options page of the Options dialog box (Tools menu).</p>	<p>Enter only values that are available in the list.</p>
<p>The Compilation Report displays a different Build Number (146) than does the About dialog box (Help menu) which displays Build Number 147.</p>	<p>The Build Number shown in the Compilation Report is correct because the Compiler was not changed in Build 147.</p>

Device Family Issues

Mercury

Issue	Workaround
<p>If your Quartus II version 1.0 or 1.1 design for a Mercury device uses the <code>altlvds_tx</code> or <code>altlvds_rx</code> megafunction, and you archived the design, you may have functional problems in your design, including inverted signals.</p>	<p>Delete the <code>altlvds_tx</code> or <code>altlvds_rx</code> megafunction from the design and replace it with the version included with the current version of the Quartus II software before compiling your design in the Quartus II software version 2.1 or later.</p>

Excalibur

Issue	Workaround
<p>You may receive the message “System Build Descriptor File missing parameter <code>programming_clock_frequency</code>” for System Build Descriptor Files (.sbd) generated in the Quartus II software version 2.0 and earlier, after selecting the Boot from Serial option in the ARM-based Excalibur MegaWizard Plug-In.</p>	<p>Rerun the ARM-based Excalibur MegaWizard Plug-In in the current version of the Quartus II software to regenerate the SBD File and correct the error.</p>
<p>You may receive the following error message when using the Excalibur Stripe Simulator (ESS) in the ModelSim software if you have not enabled VHDL93 support: “Attribute foreign has not been declared”</p>	<p>To enable VHDL93 support in the ModelSim software, uncomment the following line in your modelsim.ini file or in your ModelSim project file (.mpf): <code>; VHDL93 = 1</code> Or, you can use the <code>vcom -93</code> option when simulating the VHDL files in the ModelSim software.</p>

Issue	Workaround
<p>If you are using the Stripe-to-PLD Bridge in Excalibur EPXA10 Devices, your design may not function due to the Stripe-to-PLD Bridge lockup errata if either of the following options is turned on in the Quartus II software:</p> <p>Remove Redundant Logic Cells Perform WYSIWYG Primitive Resynthesis</p> <p>Please refer to the EPXA10 Device Errata Sheet for details on the device errata.</p>	<p>To avoid bridge lock-up, ensure that the Remove Redundant Logic Cells option is turned off for the project.</p> <p>If the Perform WYSIWYG Primitive Resynthesis option is turned on for your project, you may receive warnings that the stripe signals were not routed correctly. To eliminate the warnings, re-run the MegaWizard Plug-In Manager in the Quartus II version 2.2 software. This procedure will create an additional settings file (alt_exc_stripe.esf) to ensure that the required logic elements are implemented.</p>
<p>The SOPC Builder CD GNU Tools installer does not include the <i><GnuPro tools for ARM path>\bin</i> directory in the system path. As a result, if you run a makefile to build your software, you will receive one of the following errors:</p> <p>“arm-elf-ld: cannot open <i><path to SOPC Builder>/bin/arm-gnupro/arm9-020528//lib/gcc-lib/arm-elf/2.96-arm9-020528/crtbegin.o</i>: No such file or directory”</p> <p>or</p> <p>“Unable to Locate DLL: The dynamic link library cygwin1.dll could not be found in the specified path <i><system path></i>”</p>	<p>Perform the following steps:</p> <ol style="list-style-type: none"> 1. Manually add the path to the GnuPro tools for ARM, for example: <i><socp install dir>\bin\arm-gnupro\arm9-020528\bin</i>, to the beginning of your system path environment variable. 2. Copy the cygwin1.dll from <i><SOPC Builder install dir>\cygwin\bin</i> to <i><SOPC Builder install dir>\bin\arm-gnupro\arm9-020528\bin</i> <p>or</p> <p>Run the GnuPro tools for ARM from within the Quartus II software version 2.2 instead of using a makefile.</p>

Cyclone, Stratix & Stratix GX

Issue	Workaround
<p>For Stratix, Stratix GX, and Cyclone device families, the Quartus II software version 2.2 introduces the “Minimize Area With Chains” setting for the Auto Packed Registers option. When you compile a design with that setting, and then back-annotate the fit but demotes logic cell locations to LABs, the subsequent compilation may result in a no-fit.</p>	<p>Perform one of the following workarounds:</p> <ul style="list-style-type: none"> • If you used the “Minimize Area With Chains” setting, do not demote cell assignments to LABs. <p><i>or</i></p> <ul style="list-style-type: none"> • Save the post-fitting netlist from the first compilation (as a Verilog Quartus Mapping File (.vqm) for use in subsequent compilations. This option allows you to demote assignments to LABs.
<p>In some cases, using the Minimize Area With Chains setting for the Auto Packed Registers option can cause a no-fit due to the way a particular carry chain is packed with registers that have location constraints. You might receive one of the following messages:</p> <pre>“Error: Can't place carry chain that starts with node <node name>”</pre> <p>or</p> <pre>“Info: One or more nodes in carry chain have location assignments”</pre> <p>The usual symptom is that the carry chain is longer than one LAB, but the first and last nodes will be constrained to the same row (Y-coordinate).</p>	<p>Set the Auto Packed Registers option to OFF for all nodes in the carry chain that cannot be placed.</p>
<p>If you assign I/O pins to the same I/O Bank as pins used by the <code>alt_ddio_out</code> or <code>alt_ddio_bidir</code> megafunctions, the Quartus II software may issue a “no fit” error even though your design may not use those pins simultaneously. The Quartus II compiler automatically restricts the proximity of high data-rate pins to permit simultaneous switching of those pins.</p>	<p>Contact Altera Applications for additional information if necessary.</p>

Stratix

Issue	Workaround
<p>Versions of the Quartus II software earlier than version 2.2 did not correctly implement the following functions in DSP blocks in Stratix devices:</p> <ul style="list-style-type: none"> • Mixed sign multiplications of 19 bits and greater • Dynamic sign multiplications of 19 bits and greater • Signed multiplications greater than 36 bits 	<p>Designs that implement DSP functions must be recompiled in the Quartus II software version 2.2 or later. The Quartus II software version 2.2 will implement the design correctly, but will use more resources and have reduced performance from earlier versions.</p>

Stratix GX

The Stratix GX device family supports the following I/O standards on the RX data input pins. However, the Quartus II software version 2.2 supports only 1.5-V PCML on the RX data inputs in AC-coupled mode. If you wish to use the LVDS or LVPECL I/O standards with AC coupling, you must assign the pins to the **1.5-V PCML** I/O standard in the Quartus II software.

	RX data inputs	
	AC-coupled	DC-coupled
1.5-V PCML	✓	✓
LVDS	*	
LVPECL	*	
3.3-V PCML		

* will be supported in version 3.0

Issue	Workaround
<p>When you are using the MegaWizard Plug-In Manager (Tools menu) to generate a symbol for an <code>altgxb</code> megafunction for a protocol that is neither GigE or XAUI, you should enable the <code>rx_clkout</code> port (receiver output clock) in the MegaWizard Plug-In, unless it is being used in transmitter-only mode or if you are performing parallel loopback,</p> <p>The data signals (<code>rx_out</code>, <code>rx_patterndetect</code>, <code>rx_syncstatus</code>, <code>rx_ctrlldetect</code>, <code>rx_disperr</code>, <code>rx_errrdetect</code>, <code>rx_ala2sizeout</code>) from the receiver will then be synchronized to the <code>rx_clkout</code> clock signal.</p>	
<p>Currently the simulation models provided for the <code>altgxb</code> megafunction do not model the power-up condition correctly for simulation in other EDA simulation tools.</p>	<p>You must manually set the <code>pll_areset</code> signal to power up high in your test bench or simulation vector file. Refer to “Perform a Functional Simulation...” topics in the “Using Other EDA Simulation Tools” section of the Quartus II Help for more information.</p>

Cyclone

Issue	Workaround
<p>If you used the ACEX 2K Support Pack to compile your design in the Quartus II software version 2.1, you must change the specified device family to the Cyclone device family and recompile your design files.</p>	
<p>Altera recommends that the frequency of the external clock output of the PLLs be limited to 312 MHz.</p>	

APEX 20K, APEX 20KC, APEX 20KE & APEX II

Issue	Workaround
Regardless of the settings made in the Critical Path Settings dialog box (View menu), the Floorplan Editor will not display critical paths that have memory as their source or destination.	Use the Timing Analyzer to determine critical paths that begin or end in memory.

APEX II

Issue	Workaround
If you use the <code>altdio_in</code> or <code>altdio_bidir</code> megafunction and do not connect the <code>dataout_h</code> and <code>dataout_l</code> ports, you will receive an error message and the design will fail to compile.	Connect the <code>dataout_h</code> and <code>dataout_l</code> ports.

Design Flow Issues

Verification

Issue	Workaround
Node names for module outputs that are directly connected to inferred objects (counters, and so forth) cannot be added to an SignalTap II File (.stp).	To add such node names to an STP File, you should first assign those names to a signal bus and then add the bus to the STP File.
Projects containing an STP File that contains nodes specified for incremental routing may display the captured data incorrectly if the specified nodes fail to route. In that case, you might receive a “Can’t route SignalTap II incremental connection” message. Instead of displaying the data for the node named in the message as Unknown (X), the data will be displayed as either High (1) or Low (0).	
If you select SignalTap II in the Filter list of the Node Finder and select a bus to add to the STP File, the Quartus II software may expand the bus into individual nodes that may be removed during synthesis, resulting in an error.	Delete the nodes and recompile the project. You can select individual nodes in the Node Finder and group them in the SignalTap II window using the Group command (Edit menu).

Issue	Workaround
If you set the Sample Depth to 0 in an STP File, and use the Incremental Routing feature, you will receive a message saying “Can't make SignalTap II incremental routing connection -- target node...” and compilation will fail.	Do not use the incremental routing feature when the Sample Depth is set to 0.
If you select SignalProbe in the Filter list of the Node Finder, buses and groups of nodes may not be displayed.	Use the Design Entry filter setting instead.

Simulation

Issue	Workaround
<p>The PLLs in designs targeted to Stratix devices sometimes do not simulate correctly in other EDA simulation tools. The PLLs do not lock when you are driving the <code>altlvds_tx</code> megafunction with the <code>altlvds_rx</code> clock, or if you are driving the <code>altlvds_rx</code> megafunction with the <code>altlvds_tx</code> clock.</p>	<p>Make the following changes to the VHDL or Verilog HDL files generated by the MegaWizard Plug-In Manager and the <code>altlvds_tx</code> or <code>altlvds_rx</code> megafunctions.</p> <p>When using the <code>altlvds_tx</code> clock output to drive the <code>altlvds_rx</code> PLL, make the following changes:</p> <p>For VHDL :</p> <pre>COMPONENT altlvds_rx GENERIC (clk_src_is_pll : STRING and altlvds_rx_component : altlvds_rx GENERIC MAP (clk_src_is_pll > "on"</pre> <p>For Verilog HDL:</p> <pre>altlvds_rx_component.clk_src_is_pll = "on";</pre> <p>Or when using the <code>altlvds_rx</code> clock output to drive the <code>altlvds_tx</code> PLL, make the following changes:</p> <p>For VHDL :</p> <pre>COMPONENT altlvds_tx GENERIC (clk_src_is_pll : STRING and altlvds_tx_component : altlvds_tx GENERIC MAP (clk_src_is_pll > "on"</pre> <p>For Verilog HDL:</p> <pre>altlvds_tx_component.clk_src_is_pll = "on";</pre>

Integrated Synthesis (VHDL and Verilog HDL)

Issue	Workaround
<p>The Verilog and VHDL extractors now support the <code>translate_off</code> and <code>translate_on</code> pragmas. This change in support may cause problems in some designs that relied on the behavior of the Quartus II software versions earlier than version 2.1, which ignore pragmas. A common case is where you have a MegaWizard-generated VHDL or Verilog HDL megafunction and have added <code>translate_off</code> and <code>translate_on</code> pragmas to hide the internal details from your 3rd party synthesis tool. If you use those pragmas, the details will also be hidden from the Quartus II software, and as a result, the megafunctions will not be implemented when you compile using version 2.1 and later of the Quartus II software.</p>	
<p>Some designs that compiled successfully using the Quartus II software version 2.0 may not compile successfully using the Quartus II software version 2.1 and later. Common issues are</p> <ul style="list-style-type: none"> • Assigning to a single register in multiple Always Constructs or Process Constructs. The Quartus II software version 2.1 and later will give a multiply-driven signal error. • Width mismatches in VHDL that were not caught in the Quartus II software version 2.0. • Referring to another generic within a generic list in VHDL, for example having generic WIDTH and generic DATA(WIDTH downto 0). This feature is not officially supported in VHDL, but it is supported in many tools including the Quartus II software version 2.0. It is not supported in the Quartus II software version 2.1 and later. 	

Issue	Workaround
If you have an IP core in VHDL or Verilog HDL and your license is not set up correctly, you will get a “Can’t open design file” error.	Refer to <i>Application Note 205: Understanding Altera Licensing</i> and <i>Application Note 229: Advanced Troubleshooting for Altera Licensing</i> for more information on setting up your license.
The Quartus II software version 2.1 and later connect all nets driven by GND together, and all nets driven by VCC together. This can cause confusing error messages, as an electrical conflict on one GND net may be reported on any GND net, not necessarily the one that is actually causing the problem.	
When you instantiate a non-Verilog HDL module from a Verilog HDL design file, you must use named Parameter Value Assignments to set parameter values.	Altera recommends using a Defparam Statement to set parameter values. Ordered parameters will be ignored when instantiating non-Verilog HDL modules from a Verilog HDL design.
The Quartus II software versions 2.1 and later will give an error when you try to shift or rotate a bit vector by more than the number of bits in the vector. For example, shifting a 32-bit register by 33 bits will cause an error.	You can work around this problem by truncating or taking the modulus of the shift distance as appropriate before doing the shift or rotate.

Verilog HDL Integrated Synthesis

Issue	Workaround
Verilog-2001 mode is enabled by default. This mode can cause some issues with Verilog-1995 designs, most commonly due to new reserved words in Verilog-2001 such as <code>config</code> .	Do not use Verilog-2001 reserved words as identifiers or select Verilog-1995 on the Verilog HDL input page under HDL Input Settings of the Settings dialog box (Assignments menu).
The Quartus II software version 2.1 and later does not recognize Verilog HDL state machines. Instead it synthesizes them as generic logic. The Compiler does not report state information and you cannot control the encoding using Quartus II logic options.	A future version of the Quartus II software will recognize Verilog HDL state machines and optimize them to deliver improved performance.

Issue	Workaround
<p>The Quartus II software version 2.1 and later looks for files in an 'include compiler directive in the project root directory and the user library directories. If there is a path specified, it is interpreted as being relative to the project root directory or the user library directory.</p>	
<p>A function call in a vector range specification causes an Internal Error.</p>	
<p>Verilog HDL escaped names that look like vectors can cause problems in the Quartus II software. For example, if you have a single-bit component port named <code>\my_vector_port[3:0]</code>, the Quartus II software versions 2.1 and later will treat it as an array port.</p>	<p>You should avoid using escaped port names in the Quartus II software version 2.1 and later.</p>
<p>The Quartus II software version 2.1 and later does not allow two parameter value overrides (Defparam Statements) for a parameter. This behavior is different from the IEEE Std. 1364-2001 <i>IEEE Standard Verilog Hardware Description Language</i> manual, in which the last Defparam Statement is used if there are multiple Defparam Statements.</p>	
<p>The Quartus II software version 2.1 and later does not give an error for a Defparam Statement for a parameter that does not exist in the named module, or for a Parameter Value Assignment with more unnamed parameters than are defined in the module.</p>	
<p>Recursive Verilog HDL functions or modules, such as a module that instantiates itself, cause the Compiler in the Quartus II software version 2.1 and later to crash.</p>	

Issue	Workaround
<p>The Quartus II Verilog compiler can generate incorrect logic for certain non-blocking assignments in an Always Construct. The problem occurs when two or more assignments are made to the same indexed variable in the same Always Construct, and when the index of both assignments are a variable. In this case, the last assignment overwrites the earlier assignments. Here is an example of the problem:</p> <pre data-bbox="276 682 657 861"> always @ (posedge clk) begin b[x] <= a[x]; b[y] <= a[y]; end </pre> <p>The assignment to b[y] will overwrite the assignment to b[x]. The Quartus II software will incorrectly synthesize this code as if it was written as follows:</p> <pre data-bbox="276 1092 657 1224"> always @ (posedge clk) begin b[y] <= a[y]; end </pre>	<p>Change the non-blocking assignments to blocking assignments. Be careful to maintain the functionality of the design when you make this change.</p>

VHDL Integrated Synthesis

Issue	Workaround
<p>The Quartus II software version 2.1 and later does not synthesize a < b for user-defined enums.</p>	

Issue	Workaround
<p>The Quartus II software version 2.1 and later does not support ranges in Case Statements on an enum.</p> <p>For example:</p> <pre> type state_type is (st_a, st_b, st_c, st_d, st_e); case cur_st is ... when st_b to st_d => next_st <= st_e; ... </pre>	

EDA Integration Issues

Issue	Workaround
<p>The current version of the Quartus II software allows you to select the Synplicity Amplify software as a physical optimization tool. However, this setting is for ATOPS mode, which is currently not supported by the Amplify software.</p>	<p>Contact Synplicity for the support schedule for the Amplify software ATOPS mode.</p>
<p>The directory containing the ARM-based Excalibur stripe models changed in the Quartus II software version 2.0. This change may cause compilation scripts that were created for earlier versions of the Quartus II software to fail.</p>	<p>Edit your compilation scripts so that the models and simulation wrapper files are located in the following directory: <code>\quartus\eda\sim_lib\ excalibur\ stripe_model_<operating system></code> <code>\ModelGen\models\epxa<1 / 4 / 10>\r0\<simulator_language></code></p>
<p>There is not an option in the installation program to install the EDA tool interface for the Cadence Concept software, even though the software is supported by the Quartus II software version 2.2.</p>	<p>Select Cadence Verilog-XL in the installation to install the cadence.tcl interface script in your <code><Quartus II installation>/eda/cadence</code> directory.</p>
<p>When generating test bench files from waveform files in the Waveform Editor, if you add a single signal from a bus to the waveform file, the Quartus II software will create a signal in the test bench file with the entire bus notation as the name of the signal, instead of as a single bit on a bus.</p>	<p>Create a group in the waveform file and assign the explicit bit from the bus to the group before generating the test bench file.</p>

Customer Service Requests Resolved

Customer Service Requests resolved in this version of the Quartus II software include, but are not limited to, the following Service Request ID numbers:

Service Request ID Number	Description
10289204	Integrated HDL synthesis is generating an incorrect .vo for customer design.
10286572	Customer design error using altsyncram in Stratix.
10285904	Customer design error using altclklock.
10285476	Customer design simulator issue using Solaris 2.8 operating system.
10284406	Customer design error using altpll.
10279468	Customer design using PLL with incorrect settings.
10279316	Customer design hold time issue for DQ-DQS.
10278748	Customer EP1S40 power down issue.
10278386	Schematic design issues with bidir pins.
10277738	Customer design issue with SERDES.
10277690	Quartus II incorrectly reports that input is being unused compared to LeonardoSpectrum netlist for MAX 7000AE customer design.
10277594	Customer design synthesis issue for VHDL counter.
10276358	Customer design functional simulation issue with advance PLL lock.
10276000	Customer design dcfifo issue related to parameter mismatches.
10275794	APEX 20KE tri-state emulation issue for internal buses.
10272087	OpenCore Plus license issue when targeting cores to certain NIC configurations
10270517	Stratix timing model issue related to single memory reads from RAM.
10270477	Support bidirectional LVC MOS/LVTTL in Stratix devices enhanced.
10268909	Customer design issue with VHDL entity and architecture in different files.
10267987	Excalibur EPXA4 stripe signal masterhresp[0] routing issue.
10266017	LDRSB instruction issue related to the Excalibur ARM processor using the ESS model.
10265799	Customer design issue inserting Logic Cell with ACEX 1K device.
10265601	Customer design PLL lock issue with APEX 20KE devices.
10263449	Customer design issue using DQS.
10263423	Customer design issue related to pin placement during back-annotation.
10263117	DATA0 configuration pin-out file issue for EP1S80
10259051	Customer design issue with HEX initialization data for two ROMs packed into one ESB.
10256467	Customer design timing simulation issue with altpll - negative phase shift.
10253847	Customer design issue using altsyncram initialized to "Z"
10245267	DQS enhancement for Stratix devices.

Copyright © 2002 Altera Corporation. All rights reserved. Altera, The Programmable Solutions Company, the stylized Altera logo, specific device designations and all other words and logos that are identified as trademarks and/or service marks are, unless noted otherwise, the trademarks and service marks of Altera Corporation in the U.S. and other countries. All other product or service names are the property of their respective holders. Altera products are protected under numerous U.S. and foreign patents and pending applications, mask work rights, and copyrights.